

# 1317 NESTLE TRAIL ON STORMY LAKE,

# Haliburton

# TROY AUSTEN

REAL ESTATE TEAM

RE/MAX Professionals North Brokerage Independently Owned & Operated



### 1317 NESTLE Trail, Haliburton, Ontario K0M 1S0

Client Full **Active / Residential** 

### **1317 NESTLE TI Haliburton**

**Pending Board Approval** 

### Haliburton/Highlands East/Glamorgan 1.5 Storey/House



Water Body: Stormy Lake Type of Water: Lake

Beds Baths Kitch 1 Second

Beds (AG+BG): 3(3+0)Baths (F+H): 1(1+0)SF Fin Total: 1,920 AG Fin SF Range: 1501 to 2000 1,920/LBO provided AG Fin SF:

DOM/CDOM

Freehold/None Common Interest: \$3,652.51/2022 Tax Amt/Yr:

MLS®#: 40387914

Price: **\$1,199,999** 

Remarks/Directions

Public Rmks: Spectacular, unique cottage on Stormy lake that is unlike anything you've seen on the market. Almost 2000sq

ft of total living space, with lots of updates throughout! A 3 bedroom, 1 bathroom property with a Georgian style 500 sq ft screened-in porch that will WOW you. Imagine sitting here in the evenings with a drink, watching the sunset over the trees. Gorgeous sunsets. South-west exposure, with crown land across the bay and unhindered lake views. Beautiful reclaimed BC fir flooring, that oozes character. Stunning kitchen. Main floor primary bedroom with double doors to screened-in. porch. Gorgeous views of the lake from every room.

Boat House:

Even better in person! Prepare to be wow'd!

Directions: Follow Highway 118 to Glamorgan Road, to Alsop Trail to Nestle Trail until you see 1317.

**Common Elements** 

Balcony: Locker:

Waterfront

Features: Water Access Dock Type: **Private Docking** 

Shoreline: Clean, Natural Frontage: 105.00

Shore Rd Allow: Owned Exposure: Channel Name: Island Y/N: No

Exterior Feat: Deck(s), Fishing, Porch-Enclosed, Privacy

Construct. Material: Wood Cedar Detached Shingles Replaced: Foundation: **Poured Concrete** Prop Attached: Year/Desc/Source: Apx Age: Unknown

Property Access: Private Road, Year Round Road Rd Acc Fee:

Other Structures: Shed Winterized: **Private Drive Single Wide** 

Garage & Parking: Parking Spaces: **Driveway Spaces:** 4.0 Garage Spaces:

Cell Service, High Speed Internet Services:

Water Source: Lake/River Water Tmnt: **UV System** Sewer: Septic

Lot Size Area/Units: Acres Range: 0.50 - 1.99Acres Rent: Lot Shape: Lot Front (Ft): 105.00 Lot Depth (Ft): 0.00 Lot Irregularities: Land Lse Fee: Location: Rural

Area Influences: Lake/Pond, Quiet Area, Shopping Nearby

View: Forest, Lake, Trees/Woods Retire Com: Topography: Dry, Sloping, Wooded/Treed Fronting On:

Restrictions: Exposure: South, West

School District: **Trillium Lakelands District School Board** High School: **Haliburton Highlands Secondary School** 

Elementary School: Stuart Baker Elementary School

**Interior** 

Interior Feat: **Ceiling Fans** Security Feat: Alarm System

Crawl Space **Unfinished** Basement: Basement Fin: Cooling: None

Heating:

**Electric, Woodstove** Fireplace: /Wood Stove FP Stove Op:

Dishwasher, Microwave, Refrigerator, Stove Inclusions:

Personal belongings, the seller is working on a TBD list. Exclusions:

**Property Information** 

Common Elem Fee: No Local Improvements Fee:

PT RDAL IN FRONT OF LT 30 CON 13 GLAMORGAN CLOSED BY H281895 PT 1 19R9000; PT LT 30 CON 13 Legal Desc: GLAMORGAN PT 6 RD162; T/W H241945; S/T H241945; EXCEPT FORFEITED MINING RIGHTS, IF ANY

MUNICIPALITY OF HIGHLANDS EAST

Zoning: LSR Survey: Available/
Assess Val/Year: \$407,000/2022 Survey: Hold Over Days:

PIN: **392310170**ROLL: **460190200086700** 

Possession/Date: Flexible/ Deposit: Min 5%

ossession/Date: riexible/ Deposit: Min

List Date: 03/14/2023

List Brokerage: Re/Max Professionals North, Brokerage, Haliburton

-- -- --

Source Board: The Lakelands Association of REALTORS®

Prepared By: Amanda Tancredi, Salesperson \*Information deemed reliable but not guaranteed.\* CoreLogic Matrix

Occupant Type: Owner

Date Prepared: 03/15/2023 POWERED by itsorealestate.ca. All rights reserved.

MLS®#: 40387914 Dimensions (Metric) Room Features Room Level **Dimensions** 7' 3" X 6' 1" 2.21 X 1.85 Foyer Main Kitchen Main 12' 0" X 13' 0" 3.66 X 3.96 **Dining Room** Main 10' 0" X 15' 11" 3.05 X 4.85 4-Piece **Bathroom** Main 6' 0" X 9' 0" 1.83 X 2.74 13' 10" X 19' 0" 4.22 X 5.79 **Living Room** Main **Bedroom Primary Main** 10' 4" X 16' 2" 3.15 X 4.93 Desc: Stunning walk-out to the screen room. 10' 0" X 52' 0" 3.05 X 15.85 Sunroom Main French doors **Bedroom** Second 13' 0" X 19' 0" 3.96 X 5.79 **Bedroom** Second 13' 0" X 19' 0" 3.96 X 5.79

Protected by copyright. All use of MLS® System data is at your own risk. Information is deemed reliable but Information Technology Systems Ontario makes no warranties or representations regarding the MLS® System data.

### **UPGRADES:**

- 1. Installed new dishwasher and connect dishwasher May 2021- \$2147
- **2.** Blinds of house, June 2021 **\$1644.86**
- 3. Charcoal Filtration system, new pump and piping, May 2022- \$3945.94
- 4. WETT certify fireplace and inspection cost, May 2022- \$1289.44
- 5. Wall Installation and cover for Electrical box, August 2022- \$5300
- 6. Washer/Dryer hookup (Ready for appliances), June 2021- \$1497.25
- 7. Adjustment to water lines, added nipple and air and drain at bottom of the lake November 2022- \$380.65
- 8. New Furniture, décor, appliances (toaster, coffee maker), bedding, plates, glasses etc bought in 2021/2022- \$6,592.33
- 9. Couches, 2022- **\$4,472.54**
- 10. Entire house was painted- \$4000



## 1317 Nestle Trail Highlands East, ON

### PREPARED FOR:

INSPECTION DATE:

Thursday, March 4, 2021

PREPARED BY:

Frank Salaris



Insight360 Home Inspections 2825 IB&O Rail Trial Tory Hill, ON K0L 2Y0

705 457 5593 647 955 3466

Fax: 888 990 2566

www.insight360.ca

frank.salaris@insight360.ca







Report No. 2277

1317 Nestle Trail, Highlands East, ON March 4, 2021 www.insight360.ca

SUMMARY

ROOFING EXTERIOR

STRUCTURE

LECTRICA

HEATING

COOLING

INSULATION

**PLUMBING** 

INTERIOR

REFERENCE

This Summary outlines potentially significant issues from a cost or safety standpoint. This section is provided as a courtesy and cannot be considered a substitute for reading the entire report. Please read the complete document.

Priority Maintenance Items

### Exterior

### **ROOF DRAINAGE \ Gutters and Downspouts**

Condition: • Missing

Missing gutter, recommend installing to control water drainage around foundation walls and prevent water splashing on siding. Recommend installing slightly lower to prevent snow or ice from damaging them, also recommend installing leaf guard to prevent having to clean each fall.

Location: Throughout Exterior Roof

Task: Improve

Time: Less than 1 year Cost: Minor \$1,500 - \$2,500

### PORCHES, DECKS, STAIRS, PATIOS AND BALCONIES \ Joists

Condition: • Fastener problems

Screws can not be used for any load bearing structure components, screws can shear. Recommend replacing screws with rim joist nails on all metal fasteners within a year. Right and left staircase landings only.

Implication(s): Weakened structure | Chance of movement

Location: Exterior Staircase

Task: Improve

Time: When remodelling

Cost: Minor

### Heating

### SPACE HEATER \ Electric baseboard heater/space heater

Condition: • Missing or too few heaters

Missing heater in living room and kitchen area, recommend installing to improve comfort or consider a forced air furnace.

Implication(s): Increased heating costs | Reduced comfort

Location: First Floor Living Room Kitchen

Task: Improve

Time: When remodelling

Cost: Minor Depends on approach

Condition: • Inoperative heaters

Master bedroom space heater is inoperative, recommend further investigation suspect a loose wire.

Implication(s): No heat for building
Location: First Floor Master Bedroom

Task: Further evaluation

Time: Immediate Cost: Minor

Report No. 2277

1317 Nestle Trail, Highlands East, ON March 4, 2021

www.insight360.ca

SUMMARY

ROOFING EXTERIOR

STRUCTURE

ELECTRICA

HEATING

COOLING

INSULATION

**PLUMBING** 

INTERIOR

REFERENCE

### **CHIMNEY AND VENT \ Metal chimney or vent**

Condition: • Inadequate chimney height above roof

Chimney must be a least 2ft higher than roof structure within 10 ft horizontal, Recommend adding an extensions to chimney to meet WETT inspection requirements.

Implication(s): Equipment not operating properly | Hazardous combustion products entering home

Location: Exterior Roof

Task: Improve Time: Immediate Cost: Minor

### WOOD STOVE \ Cabinet, door and clearances

Condition: • Floor - combustible clearance inadequate

Living room wood stove-

Inadequate floor protection, ember pad must extend 18" in front and 8" on each side and back of wood stove.

Wood stove flue pipe must also have 3 screws at each connection.

Implication(s): Increased fire hazard Location: First Floor Living Room

Task: Improve Time: Immediate Cost: Minor

### Insulation and Ventilation

### FOUNDATION \ Crawlspace floor

Condition: • No vapor barrier

Crawlspace is missing a floor vapor barrier on the floor, recommend installing and taping / gluing all seams and perimeter walls to reduce humidity and increase comfort. Venting crawlspace during the summer months will also reduce the amount of humidity in the crawlspace. Some mildew noted on floor joist and floor sheathing.

Implication(s): Chance of condensation damage to finishes and/or structure

Location: Crawl Space

Task: Improve

Time: When remodelling

Cost: Minor

### **Plumbing**

### **WASTE PLUMBING \ Traps - installation**

Condition: • Tailpiece (fixture outlet pipe) too long

Tailpiece too long under kitchen sinkand bathroom sink, recommend adding a trap below kitchen sink in the future. When the tailpiece is too long, risk of trap in floor space flushing out and allowing sewer gasses to enter. Monitor and repair if necessary, if sewer gasses are noted simply pour a glass of water down the drain.

Implication(s): Sewer gases entering the building

Location: First Floor Kitchen Bathroom

Report No. 2277

HEATING

COOLING

1317 Nestle Trail, Highlands East, ON March 4, 2021 **EXTERIOR** 

STRUCTURE

INSULATION PLUMBING INTERIOR

www.insight360.ca

SUMMARY REFERENCE

Task: Improve Monitor Time: If necessary

ROOFING

Cost: Minor

### WATER TREATMENT SYSTEM \ General notes

Condition: • UV filter is needed for good potable water whenever drawing water from the lake, recommend installing

within a year.

Location: Crawl Space

Task: Improve

Time: Less than 1 year

Cost: Minor

### Interior

### STAIRS \ Guardrails

Condition: • Missing

Second floor staircase is missing spindles, recommend providing for the safety of young children.

Implication(s): Fall hazard

Location: Second Floor Staircase

Task: Improve

Time: When remodelling

Cost: Minor

### **EXHAUST FANS \ General notes**

Condition: • Missing

Missing exhaust fan in bathroom, recommend installing when remodeling to prevent moist air from creating mildew and rot. Recommend opening a window until exhaust fan is installed.

Implication(s): Chance of condensation damage to finishes and/or structure

Location: First Floor Bathroom

Task: Provide

Time: When remodelling Cost: Minor \$300 - \$600

This concludes the Summary section.

The remainder of the report describes each of the home's systems and also details any recommendations we have for improvements. Limitations that restricted our inspection are included as well.

The suggested time frames for completing recommendations are based on the limited information available during a pre-purchase home inspection. These may have to be adjusted based on the findings of specialists.

Home Improvement - ballpark costs

# MLL Plumbing Patrick Blaney 705-790-6370 MLLPlumbing@outlook.com


Date: Client Name: Address:

Phone Number:

Item Description	Quantity	Price	Total
Travel (assessment)	2h/3	95/61	1900
installation	21123	95/1	190.00
1abour	0h3	95/hr	255,00
uv promat with contralor, build 7 steene-			775/ 99
240 convertible Jet purp, Aquatie			
filter housings with bracketis)			
Particle filler and charcoal Filter.			
associated ports le ger cleus.			
bushing, adopter ball volves etc.			
organs journes sures			
West Decembries			
Work Description (California)			
renave pressure tank, pump, friters			
and pipe unstall wen weter			
treatient 34 selv.			
14			
· ONIV			
VAXIII			
12000			
400			
4			
	SubT	Total:	31101 00
			2471-14
Notes:	HS	)1;	4) 5-45

Total:

Amount Owing:



RD-162.

PART

PLAN OF SURVEY

PART OF LOT 30, CON. XIII
TOWNSHIP OF GLAMORGAN
PROVISIONAL COUNTY OF HALIBURTON

SCALE: 1" = 100'

RECEIVED AND DEPOSITED AS

PLAN R. P. 162

Jeon a Jackson

REGISTRAR FOR THE
REGISTRY DIVISION OF THE
PROVISIONAL COUNTY
OF HALIBURTON

RO-162

EI

I REQUIRE THIS PLLAN TO BE DEPOSITED UNDER PART II OF THE REGISTRY ACT.

JUNE 17, 1970

At Charles

H.C. BISHOP

SURVEYOR'S CERTIFICATE

I HEREBY CERTIFY THAT

I THIS SURVEY AND PLAN ARE CORRECT AND IN ACCORDANCE WITH THE SURVEYS ACT AND THE REGISTRY ACT AND THE REGULATIONS MADE THEREUNDER.

2. THIS SURVEY WAS COMPLETED MAY 12,1970.

HALIBURTON, ONT., MAY 18 , 1970 H CLIBBY BISHOP

STORMY

H CURRY BISHOP ONTARIO LAND SURVEYOR BEARINGS ARE

BEARING NOTE

BEARINGS ARE ASTRONOMIC AND DERIVED FROM AND REFERRED TO THE N76°12'W OF THE NORTHERLY LIMIT OF LOTS 7 & 8, REGISTERED PLAN 384

